

Drinking water Sampling and Analysis for Lead (Pb)

Codes for sampling points.

- WC = water cooler (chiller unit)
- CF = classroom faucet
- KC = kitchen faucet, cold
- EC = home economics room, cold
- IM = Ice Machine
- NS = nurse's office sink
- SC = service connector
- LAV = Lavatory sink (cold)
- SS = Slop Sink (i.e. Custodial closet)
- FSC = Faculty Sink Cold

How to sample?

Basic sampling protocol: This is an overview of the sampling procedures.
 Determine which outlets will be sampled. Determine priorities and code outlets appropriately.
Outlets must be inactive for at least 8 hours before testing. (Overnight is best.)
 Take a "first draw" 250 ml** sample at each outlet.

School District Name: Jamesville DeWitt CSD

Building Name: Middle School

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. sink, DF)	DF - model No.)	Notes:
1	First Flush	9/16/2016 05:29	SW	KC		MT Slicer
2	" "	9/16/2016 05:31	W	KC		oven wall
3	" "	9/16/2016 05:32	SW	KC		Pot Filler
4	" "	9/16/2016 05:33	center	KC		Center isle sink
5	" "	9/16/2016 05:35	NW	KC		Steam kettle filler
6	" "	9/16/2016 05:38	N	KC		Pot Sink lft
7	" "	9/16/2016 05:38	N	KC		Pot sink rt
8	" "	9/16/2016 05:41	NE	KC		Hand sink by pot wash
9	" "	9/16/2016 05:42	SE	KC		hand sink
10	" "	9/16/2016 05:43	E	LAV		kitchen lavatory
11	" "					
12	" "					
13	" "					
14	" "					
15	" "					
16	" "					
17	" "					
18	" "	9/16/2016 05:57	NW lft	LAV		men's pool lkr rm
19	" "	9/16/2016 05:58	NE rt	LAV		men's pool lkr rm
20	" "					
21	" "					
22	" "					
23	" "					
24	" "					
25	" "					
26	" "					
27	" "					
28	" "	9/16/2016 06:03	NW	LAV		Wo pl lkr rm
29	" "	9/16/2016 06:04	NE	LAV		Wo pl lkr rm
30	" "					
31	" "					
32	" "					
33	" "	9/16/2016 06:17	E - S	WC - A		pl lobby
34	" "	9/16/2016 06:17	S - E	WC - B		pl lobby
35	" "	9/16/2016 06:18	N	LAV		Wo pl lobby
36	" "	9/16/2016 06:19	N	LAV		M pl lobby
37	" "	9/16/2016 06:24	S	LAV		Aux Gym
38	" "					
39	" "					

40	" "				
----	-----	--	--	--	--

Drinking water Sampling and Analysis for Lead (Pb)

Page 2 of 4

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. sink, DF)	(if DF - model No.)	Notes
41	First Flush	9/16/2016 06:29	SW	LAV		W Aux Gym lkr Rm
42	" "					
43	" "					
44	" "					
45	" "					
46	" "	9/16/2016 06:34	W	LAV		M Aux gym lkr rm
47	" "					
48	" "	9/16/2016 06:38	S	WC A	Elkay	Aux Gym
49	" "	9/16/2016 06:37	S	WC B	Elkay	Aux Gym
50	" "	9/26/2016 06:45	S	fountain		W main gym lckr rm
51	" "					
52	" "					
53	" "					
54	" "					
55	" "					
56	" "					
57	" "					
58	" "					
59	" "					
60	" "	9/16/2016 06:57	N	LAV - lft		W main gym lkr rm
61	" "	9/16/2016 05:59	N	LAV - rt		W main gym lkr rm
62	" "	9/16/2016 06:59	N	LAV - office		W main gym lkr rm
63	" "					
64	" "	9/16/2016 07:03	N	CF		Orchestra rm
65	" "					
66	" "					
67	" "					
68	" "					
69	" "					
70	" "					
71	" "					
72	" "					
73	" "	9/16/2016 07:14	NW	fountain		M main Gym lkr rm
74	" "					
75	" "	9/16/2016 07:15	E	LAV - RT		M main Gym lkr rm
76	" "	9/16/2016 07:19	S	LAV		M Team Rm
77	" "	9/16/2016 07:21	S	LAV		W team rm
78	" "	9/16/2016 07:24	W-S	EC A		RM 15
79	" "	9/16/2016 07:24	N	EC B		RM 15
80	" "	9/16/2016 07:25	S	ECC		RM 15

Drinking water Sampling and Analysis for Lead (Pb)

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. sink, DF)	(if DF - model No.)	Notes;
81	First Flush	9/16/2016 7:27	W	EC		Rm 15 office
82	" "	9/20/2016 05:26	House 3 women's A	LAV		North
83	" "	9/20/2016 05:26	House 3 women's B	LAV		North
84	" "	9/20/2016 05:26	House 3 women's C	LAV		North
85	" "	9/20/2016 05:26	House 3 women's D	LAV		North
86	" "	9/20/2016 05:30	House 3	WC	Elkay	left
87	" "	9/20/2016 05:30	House 3	WC	Elkay	right
88	" "	9/20/2016 05:32	House 3 men's A	LAV		south
89	" "	9/20/2016 05:32	House 3 men's B	LAV		south
90	" "	9/20/2016 05:32	House 3 men's C	LAV		south
91	" "	9/20/2016 05:32	House 3 men's D	LAV		south
92	" "	9/20/2016 05:36	301	CF		HS 3 south
93	" "	9/20/2016 05:38	301	CF		isle
94	" "	9/20/2016 05:40	312	CF		SE HS 3
95	" "	9/20/2016 05:40	312	CF		Isle
96	" "	9/20/2016 05:42	311	CF		east
97	" "	9/20/2016 05:44	201	CF		S-W HS 2
98	" "	9/20/2016 05:45	25	CF		north
99	" "	9/20/2016 05:46	House 2 men's A	LAV		West
100	" "	9/20/2016 05:46	House 2 men's B	LAV		West
101	" "	9/20/2016 05:46	House 2 men's C	LAV		West
102	" "	9/20/2016 05:46	House 2 men's D	LAV		West
103	" "	9/20/2016 05:50	House 2 left	WC	Elkay	South
104	" "	9/20/2016 05:50	House 2 Right	WC	Elkay	South
105	" "	9/20/2016 05:51	Hs 2 Women's A	LAV		East
106	" "	9/20/2016 05:51	Hs 2 Women's B	LAV		East
107	" "	9/20/2016 05:51	Hs 2 Women's C	LAV		East
108	" "	9/20/2016 05:51	Hs 2 Women's D	LAV		East
109	" "	9/20/2016 05:54	211 office	CF		north hs 2
110	" "	9/20/2016 05:55	212	CF		South hs 2
111	" "	9/20/2016 05:55	212 isle	CF		house 2
112	" "	9/20/2016 05:57	26 - isle	CF		house 2
113	" "	9/20/2016 05:58	112 north	cf		house 1
114	" "	9/20/2016 06:02	101 east	CF		house 1
115	" "	9/20/2016 06:05	102-West	CF		house 1
116	" "	9/20/2016 06:07	103 west	cf		house 1
117	" "	9/20/2016 06:08	105 South	CF		house 1
118	" "	9/20/2016 06:08	104 South	CF		house 1
119	" "	9/20/2016 06:10	108 West	CF		house 1
120	" "	9/20/2016 06:11	109 West	CF		house 1

Drinking water Sampling and Analysis for Lead (Pb)

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. sink, DF)	(if DF - model No.)	Notes
121	First Flush	9/20/2016 06:13	110 West	CF		House 1
122	" "	9/20/2016 06:14	111 West	CF		
123	" "	9/20/2016 06:10	A	LAV		HS 1 Men's North
124	" "	9/20/2016 06:10	B	LAV		HS 1 Men's North
125	" "	9/20/2016 06:10	C	LAV		HS 1 Men's North
126	" "	9/20/2016 06:10	D	LAV		HS 1 Men's North
127	" "	9/20/2016 06:14	Left - west	WC	Elkay	House 1
128	" "	9/20/2016 06:14	Right - west	WC	Elkay	House 1
129	" "	9/20/2016 06:17	A	LAV		HS 1 Wo's South
130	" "	9/20/2016 06:18	B	LAV		HS 1 Wo's South
131	" "	9/20/2016 06:18	C	LAV		HS 1 Wo's South
132	" "	9/20/2016 06:18	D	LAV		HS 1 Wo's South
133	" "	9/20/2016 06:20	113 West	CF		House 1
134	" "	9/20/2016 06:22	Library office N	FS		
135	" "	9/20/2016 06:24	New Tech Room	CF		West
136	" "	9/20/2016 06:25	Across from LGIR	DF		East
137	" "	9/20/2016 06:28	17 - E-S	CF		
138	" "	9/20/2016 06:30	402 - west	CF		
139	" "	9/20/2016 06:30	401-West	CF		
140	" "	9/20/2016 06:34	403-West	CF		
141	" "	9/20/2016 06:34	404 - West	CF		
142	" "	9/20/2016 06:35	405 - West	CF		
143	" "	9/20/2016 06:35	406 - West	CF		
144	" "	9/20/2016 06:37	407 - West	CF		
145	" "	9/20/2016 06:37	408-West	CF		
146	" "	9/20/2016 06:38	409 - East	CF		
147	" "	9/20/2016 06:38	410 - East	CF		
148	" "	9/20/2016 06:39	411 - East	CF		
149	" "	9/20/2016 06:40	Office - east	FSC		House 4
150	" "	9/20/2016 06:41	Left - South	WC		House 4
151	" "	9/20/2016 06:41	Right - South	WC		House 4
152	" "	9/20/2016 06:43	412 - East A	LAV		Hs4 women's
153	" "	9/20/2016 06:43	412 - East B	LAV		Hs4 women's
154	" "	9/20/2016 06:43	412 - East C	LAV		Hs4 women's
155	" "	9/20/2016 06:45	412 - West A	LAV		Hs4 men's
156	" "	9/20/2016 06:45	412 - West B	LAV		Hs4 men's
157	" "	9/20/2016 06:45	412 - West C	LAV		Hs4 men's
158	" "	9/20/2016 06:48	North	WC	Elkay	House 4
159	" "	9/20/2016 06:52	Art Rm 3 - A East	CF		House 4
160	" "	9/20/2016 06:53	Art Rm 3 - B South	CF		House 4

Drinking water Sampling and Analysis for Lead (Pb)

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. sink, DF)	(if DF - model No.)	Notes;
161	First Flush	9/20/2016 06:53	Art rm 3-C south	CF		House 4
162	" "	9/20/2016 06:57	Art rm 3- D south	CF		House 4
163	" "	9/21/2016 06:25	Front entry	WC	Elkay	
164	" "	9/21/2016 06:25	Front entry	LAV		Women's rm Lft
165	" "	9/21/2016 06:25	Front entry	LAV		Women's rm Rt
166	" "	9/21/2016 06:30	Cafeteria	WC	Elkay EZ H2O	
167	" "	9/21/2016 06:30	Art Rm 1	CF		West
168	" "	9/21/2016 06:30	Art Rm 1	CF		South
169	" "	9/21/2016 06:31	Clay room	CF		
170	" "	9/21/2016 06:31	Art rm 2	CF		East
171	" "	9/21/2016 06:30	Art Rm 2	CF		West
172	" "	9/21/2016 06:35	Nurses office	LAV		
173	" "	9/21/2016 06:35	Nurses office	NS		
174	" "	9/21/2016 06:38	Dock	SS		
175	" "	9/21/2016 06:38	Dock	IM		
176	" "	9/21/2016 06:40	kitchen	IM		
177	" "	9/22/2016 04:58	E	LAV - Lft		Men's main Gym lkr rm
178	" "					
179	" "					
180	" "					
181	" "					
182	" "					
183	" "					
184	" "					
185	" "					
186	" "					
187	" "					
188	" "					
189	" "					
190	" "					
191	" "					
192	" "					
193	" "					
194	" "					
195	" "					
196	" "					
197	" "					
198	" "					
199	" "					
200	" "					