

Drinking water Sampling and Analysis for Lead (Pb)

Codes for sampling points.

- WC = water cooler (chiller unit)
- CF = classroom faucet
- KC = kitchen faucet, cold
- EC = home economics room, cold
- IM = Ice Machine
- NS = nurse's office sink
- SC = service connector
- LAV = Lavatory sink (cold)
- SS = Slop Sink (i.e. Custodial closet)
- FSC = Faculty Sink Cold

How to sample?

Basic sampling protocol: This is an overview of the sampling procedures.

Determine which outlets will be sampled. Determine priorities and code outlets appropriately.

Outlets must be inactive for at least 8 hours before testing. (Overnight is best.)

Take a "first draw" 250 ml** sample at each outlet.

School District Name: Jamesville DeWitt CSD

Building Name: Tecumseh Elementary

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. sink, DF)	(if DF - model No.)	Notes;
1	First Flush	09/22/16 05:08	Kitchen dishmachine	kc		
2	" "	09/22/16 05:08	Kitchen hand sink	kc		
3	" "	09/22/16 05:08	kithchen pot sink left	kc		
4	" "	09/22/16 05:08	kitchen pot sink right	kc		
5	" "	09/22/16 05:08	kitchen prep isle lft	kc		
6	" "	09/22/16 05:08	kitchen prep isle rt	kc		
7	" "	09/22/16 05:20	cafateria	wc	elkay	
8	" "	09/22/16 05:22	123	cf		
9	" "	09/22/16 05:24	124	cf		
10	" "	09/22/16 05:25	125	cf		
11	" "	09/22/16 05:26	126	cf		
12	" "	09/22/16 05:28	130	cf		
13	" "	09/22/16 05:30	PPC	cf		
14	" "	09/22/16 05:27	128	cf		
15	" "	09/22/16 05:30	131	cf		
16	" "	09/22/16 05:30	132	cf		
17	" "	09/22/16 05:32	2nd grd girls	LAV		left
18	" "	09/22/16 05:34	2nd grd girls	LAV		center
19	" "	09/22/16 05:35	2nd grd girls	LAV		right
20	" "	09/22/16 05:32	2nd grd corridor	WC		
21	" "	09/22/16 05:40	2nd grd boys	LAV		left
22	" "	09/22/16 05:40	2nd grd boys	LAV		center
23	" "	09/22/16 05:36	2nd grd boys	LAV		right
24	" "	09/22/16 05:37	133	CF		
25	" "	09/22/16 05:41	102	wc		
26	" "	09/22/16 05:40	101	wc		
27	" "	09/22/16 05:40	101	cf		
28	" "	09/22/16 05:41	102	CF		
29	" "	09/22/16 05:42	104	wc		
30	" "	09/22/16 05:42	104	cf		
31	" "	09/22/16 05:45	103	wc		
32	" "	09/22/16 05:45	103	cf		
33	" "	09/22/16 05:47	106	cf		
34	" "	09/22/16 05:47	106	wc		
35	" "	09/22/16 05:48	105	wc		
36	" "	09/22/16 05:49	105	cf		
37	" "	09/22/16 05:50	108	wc		
38	" "	09/22/16 05:50	108	cf		
39	" "	09/22/16 05:51	107	wc		

40	" "	09/22/16 05:52	107	cf	
----	-----	----------------	-----	----	--

Drinking water Sampling and Analysis for Lead (Pb)

Page 2 of 4

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. fink, DF)	(if DF - model No.)	Notes;
41	First Flush	09/22/16 05:50	110	cf		
42	" "	09/22/16 05:50	110	wc		
43	" "	09/22/16 05:54	109	cf		
44	" "	09/22/16 05:53	109	wc		
45	" "	09/22/16 05:55	112	cf		
46	" "	09/22/16 05:55	112	wc		
47	" "	09/22/16 05:57	Art Rm	cf		east left
48	" "	09/22/16 05:57	Art Rm	Cf		east center
49	" "	09/22/16 06:00	Art Rm	cf		east right
50	" "	09/22/16 06:00	Art Rm	cf		West right
51	" "	09/22/16 06:00	Art Rm	cf		west center
52	" "	09/22/16 06:01	Art Rm	cf		west left
53	" "	09/22/16 06:01	114	cf		
54	" "	09/22/16 06:05	Staff	LAV		
55	" "	09/22/16 06:02	Disabled	LAV		
56	" "	09/22/16 06:05	115	cf		
57	" "	09/22/16 06:05	115	wc		
58	" "	09/22/16 06:08	boys - gym right	LAV		
59	" "	09/22/16 06:08	Boys gym left	LAV		
60	" "	09/22/16 06:10	120 - eyewash sink	NS		
61	" "	09/22/16 06:10	120	ns		
62	" "	09/22/16 06:12	coridor by nurse	wc		
63	" "	09/22/16 06:15	121	fsc		
64	" "	09/22/16 06:15	116	cf		
65	" "	09/22/16 06:16	girls locker rm	LAV		
66	" "	09/22/16 06:20	119	cf		
67	" "	09/22/16 06:20	117	cf		
68	" "	09/22/16 06:20	118	cf		
69	" "	09/22/16 06:20	boys locker rm	wc		
70	" "	09/22/16 06:21	boys locker rm	LAV		
71	" "	09/22/16 06:25	girls locker rm	wc		
72	" "	09/22/16 06:26	146	wc		
73	" "	09/22/16 06:26	146	cf		
74	" "	09/22/16 06:25	144	cf		
75	" "	09/22/16 06:25	144	wc		
76	" "	09/22/16 06:30	4th grd girls	LAV		right
77	" "	09/22/16 06:30	4th grd girls	LAV		center
78	" "	09/22/16 06:30	4th grd girls	LAV		left
79	" "	09/22/16 06:32	4th grd boys	LAV		left
80	" "	09/22/16 06:32	4th grd boys	LAV		center

Drinking water Sampling and Analysis for Lead (Pb)

Sample No.	Description	Date/Time Sampled	Location of Water Outlet (i.e. Rm #, near xx)	Type of Outlet (i.e. sink, DF)	(if DF - model No.)	Notes;
81	First Flush	09/22/16 06:32	4th grd boys	LAV		right
82	" "	09/22/16 06:33	145	WC		
83	" "	09/22/16 06:33	145	CF		
84	" "	09/22/16 06:35	147	WC		
85	" "	09/22/16 06:35	147	CF		
86	" "	09/22/16 06:40	Library	CF		
87	" "	09/22/16 05:15	employ lckr rm	LAV		
88	" "	09/22/16 06:07	gym lckr rm girls	LAV		left
89	" "	09/22/16 06:45	outside	WC		
90	" "	09/22/16 06:07	gym lckr rm girls	LAV		right
91	" "	09/22/16 06:47	4th grd corridor	WC	Elkay	left
92	" "	09/22/16 06:47	4th grd corridor	WC	Elkay	right
93	" "	09/22/16 06:47	hall by rm 116	WC		
94	" "					
95	" "					
96	" "					
97	" "					
98	" "					
99	" "					
100	" "					
101	" "					
102	" "					
103	" "					
104	" "					
105	" "					
106	" "					
107	" "					
108	" "					
109	" "					
110	" "					
111	" "					
112	" "					
113	" "					
114	" "					
115	" "					
116	" "					
117	" "					
118	" "					
119	" "					
120	" "					